WA-I-507 Brick House

Late 19th century

St. James Village

Private

The Brick House is a three-bay by two-bay structure which appears to have been an early brick farm house that has been remodeled recently. Currently the house has a gable and main facade with a side entrance. Two windows are on the first story and three windows on the second story underneath the gable roof of this main section. On the north side of this section is a wing which may be the original ell of the farmhouse. The wing is covered with ivy and has a modern picture window on the first floor. On the south side of the main section is a recent addition with a large picture on the first floor and a small window on the second floor.

Maryland Historical Trust State Historic Sites Inventory Form

Magi	No.	
DOE	yes	no

1. Nam	e (indicate pr	eferred name)		
historic				
and/or common	Brick house			
2. Loca	ation			
street & number	Sumerlin Drive,	2 milè west of Rt. 6	65	not for publication
city, town St	. James Village	vicinity of	congressional district	sixth
state Mary	land	county	Washington	
3. Clas	sification			
Category districtX building(s) structure site object	Ownership public private both Public Acquisition in process being considerednot_applicable	Status X occupied unoccupied work in progress Accessible yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
	er of Prope	rty (give names an	nd mailing address	es of <u>all</u> owners)
street & number	. Haddock		telephone 1	no.:
city, town		state	and zip code	
	ation of Leg	al Description	on	
courthouse, regi	stry of deeds, etc. Wa	shington County Cou	rthouse	liber
street & number	Washington Stree	t		folio
city, town Ha	gerstown		state	Maryland
6. Rep	resentation	in Existing	Historical Sur	veys
itle	·			
date			federal sta	ate county loca
depository for su	urvey records			
city, town			state	_

7.	Descr	iption	

Survey	No.	WA-I-507
--------	-----	----------

Check one Check one excellent deteriorated unaltered original site good ruins altered moved date of move fair unexposed	good ruins		<u> </u>	
--	------------	--	----------	--

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

The brick house is a three-bay by two-bay structure which appears to have been an early brick farm house that has been remodeled recently. Currently the house has a gable and main facade with a side entrance. Two windows are on the first story and three windows on the second story underneath the gable roof of this main section. On the north side of this section is a wing which may be the original ell of the farm house. The wing is covered with ivy and has a modern picture window on the first floor. On the south side of the main section is a recent addition with a large picture on the first floor and a small window on the second floor. The original section appears to have been built in the late 19th century.

The property is located on Sumerlin Drive, .2 mile west of Rt. 65 in St. James Village. St. James Village is a large subdivision of modern homes. This older house sits in the middle of the subdivision. The current main facade faces east.

The property is built of brick in stretcher bond. A brick chimney rising from the gable end which contains the entrance indicates that the house probably was built in the L-shape farm house style of the region. However, several remodelings have occurred to the house and have inwolved the application of modern materials.

PeriodAreas of Significance—C— prehistoric— archeology-prehistoric— 1400–1499— archeology-historic— 1500–1599— agriculture— 1600–1699— architecture— 1700–1799— art— 1800–1899— commerce— 1900–— communications		archeology-prehistoric archeology-historic agriculture architecture art commerce	Heck and justify below community planning conservation economics education engineering exploration/settlemen industry invention	law literature military muslc t philosophy politics/government	religion science sculpture social/ humanitarian theater transportation other (specify)
Specific	dates		Builder/Architect		
check:	an	cable Criteria:A ad/or cable Exception:A	_	EFG	
 		of Significance:			
Prepare support	e both	a summary paragraph o	of significance and a	a general statement o	f history and

Based on the MHT Survey Matrix, this is a mid-level site. It appears that 20th century alterations have significantly altered a mid-to-late 19th century regional farmhouse at this site.

9. Major Bibliographical References

Survey No. WA-I-507

10.	Geograp	hical Data			
Quadran	gle name	complete UTM refer		Quadranç	jle scale
AZone	Easting	Northing	B Zone	Easting	Northing
C E G			D		
Verbal t	boundary descrip	tion and justification			
	states and count	ies for properties overl	apping state or co	unty boundarie:	code
state		code	county		code
11.	Form Pr	epared By			
name/title	e Joe Getty				
organiza	tion Maryland	Historical Trust	da	nte May 1983	
street & number 21 State Circle			tel	lephone	
city or to	wn Annapoli	5	sta	ate Maryland	

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:


Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438





- Brick House WA-I-507 1. Washington County, Maryland
- 3. Joe Getty
- 4. May 1983 5.
- Maryland Hist. Trust, Annapolis, Md.
- 6. East Elevation; camera facing northeast 7. 1/1